



S.C. Occupational Safety and Health Administration

25 MOST FREQUENTLY CITED CONSTRUCTION STANDARDS

January 1, 2014- December 31, 2014

Rank	# Cited	Standard	Hazard Description
1	42	1926.602(a)(9)(i)	No audible alarms for material handling equipment
2	38	1.12(a)	Failed to furnish a place of employment free of recognized hazards
3	32	1910.1200(f)(5)	Containers of hazardous chemicals not properly labeled, tagged, or marked
4	29	1910.1200(h)(1)	Inadequate training on hazardous chemicals
5	29	1926.152(g)(9)	No signs posted to prohibit smoking near flammable and combustible liquids
6	26	1910.1200(e)(1)	No written Hazard Communication Program
7	25	1910.1200(e)(1)(i)	No list of hazardous chemicals
8	24	1926.451(g)(4)(i)	Inadequate guardrails on open sides and ends of scaffold platforms
9	24	1926.601(b)(4)	No vehicle shall be operated with an obstructed view
10	21	1926.501(b)(1)	Fall Protection – unprotected sides and edges/residential construction
11	20	1910.1200(g)(1)	No SDS for hazardous chemicals
12	19	1910.178(l)(4)(iii)	No evaluation of forklift operator’s performance conducted at least every 3 years
13	19	1926.602(a)(9)(ii)	Earthmoving or compacting equipment used when the rear view is obstructed
14	18	1926.300(b)(2)	Unguarded reciprocating, rotating or moving parts of equipment
15	16	1926.453(b)(2)(v)	No body belt when working from an aerial Lift
16	12	1926.404(b)(1)(ii)	No approved ground-fault circuit interrupters
17	12	1926.405(b)(2)	No covers provided for pull boxes, junction boxes, and fittings
18	12	1926.602(c)(1)(vi)	Failed to ensure industrial trucks meet the requirements ANSI B56.1-1969
19	11	1926.652(a)(1)	No protection from cave-ins for employees in an excavation
20	10	1926.451(c)(1)(ii)	Failed to meet tie-in requirements for supported scaffolds
21	9	1926.501(b)(13)	No fall protection for employees working above 6 ft in residential construction
22	8	1926.405(b)(1)	Unused openings in cabinets, boxes, and fittings not effectively closed
23	8	1926.501(b)(10)	No fall protection for employees working above 6 feet in residential construction
24	7	1926.451(e)(1)	Ladder not provided to access scaffold
25	7	1926.501(b)(14)	No fall protection for employees working above 6 ft on, at, or near wall openings

January 1, 2014- December 31, 2014